



Republic of the Philippines
 Department of Agriculture
PHILIPPINE COUNCIL FOR AGRICULTURE AND FISHERIES
 Department of Agriculture Compound
 Elliptical Road, Diliman, Quezon City
 Tel. No. (02) 8928-8751 to 64 locals 2601-2625, email: pcafofficial@pcaf.da.gov.ph

April 1, 2024

**NOTICE OF AWARD
 No. 2024-029**

MR. JONATHAN C. GANITANO
 Proprietor
 TOP PREMIERE ENTERPRISE
 1918 Piy Margal St.
 Sampaloc, Manila

Dear **Mr. Ganitano:**

With reference to your quotation for the **ONE (1) LOT REPAIR/REPLACEMENT OF PARTS OF AIR CONDITIONING UNITS**, we are pleased to confirm the award to your firm for the total amount of **NINETY-SEVEN THOUSAND PESOS (Php 97,000.00)**, inclusive of appropriate taxes and fees, with the following specifications:

Item Description	QTY	Unit	Total Cost
REPAIR/REPLACEMENT OF PARTS OF THE FOLLOWING AIR CONDITIONING UNITS:	1 LOT		97,000.00
1. Repair of Carrier 1.5 HP wall mounted inverter air conditioning unit located COA	1	UNIT	
Scope of Work:			
1. Repair of PCB main board assembly.			
2. Repair and reconditioning of PBC Assembly.			
3. Supply and installation of diodes.			
4. Supply and installation of IC's.			
5. Leak testing and leak brazing.			
6. Flushing of refrigerant system using freon gas 141b.			
7. Flushing of refrigerant system using nitrogen gas.			
8. Vacuuming and recharging of freon gas.			
9. Labor cost.			
10. Test and observation.			
VAT			
SUB-TOTAL			13,000.00
2. Repair of Carrier 2.5 HP wall mounted inverter type air conditioning unit located at PMKMD	1	UNIT	
Scope of Work:			
1. Leak test and leak brazing.			
2. Flushing of refrigerant system using freon gas 141b.			
3. Flushing of refrigerant system using nitrogen gas.			
4. Vacuuming and recharging of freon gas.			
5. Labor cost			
6. Test and observation.			
VAT			
SUB-TOTAL			8,000.00



3. Repair of Carrier 3.0 TR ceiling mounted type air conditioning unit located at Apacible Conference Room B.	1	UNIT	
Scope of Work:			
1. Supply and installation of PCB manual switch.			
2. Conversion of control to universal board assembly.			
3. Rewiring of PCB assembly.			
4. Leak test and leak brazing.			
5. Flushing of refrigerant system using freon gas 141b.			
6. Flushing of refrigerant systems using nitrogen gas.			
7. Vacuuming and recharging of freon gas.			
8. Labor cost			
9. Test and observation.			
VAT			
SUB-TOTAL			15,000.00
4. Repair of Carrier 3.0 TR floor mounted type air conditioning unit located at BAC Conference Room	1	UNIT	
Scope of Work:			
1. Supply and installation of PCB manual switch.			
2. Conversion of control to universal board assembly.			
3. Rewiring of PCB assembly.			
4. Leak test and leak brazing.			
5. Flushing of refrigerant system using freon gas 141b.			
6. Flushing of refrigerant system using nitrogen gas.			
7. Vacuuming and recharging of freon gas.			
8. Labor cost			
9. Test and observation.			
VAT			
SUB-TOTAL			15,000.00
5. Repair of Carrier 3.0 HP wall mounted inverter type air conditioning unit located at PDD	1	UNIT	
Scope of Work:			
Supply and installation of 30 amps. Circuit breaker.			
Leak test and leak brazing.			
Flushing of refrigerant system using freon gas 141b			
Flushing of refrigerant system using nitrogen gas.			
Vacuuming and recharging of freon gas.			
Test and observation			
VAT			
SUB-TOTAL			10,000.00
6. Repair of Carrier 3.0 HP wall mounted inverter type air conditioning unit located at PDD	1	UNIT	
Scope of Work:			
1. Leak test and leak brazing.			
2. Flushing of refrigerant system using freon gas 141b.			
3. Flushing of refrigerant system using nitrogen gas.			
4. Vacuuming and recharging of freon gas.			
5. Test and observation			
VAT			
SUB-TOTAL			8,000.00



7. Repair of Carrier 3.0 HP wall mounted inverter type air conditioning unit located at PDD.	1	UNIT	
Scope of Work:			
Supply and installation for 30 amps circuit breaker.			
Supply and installation of receiver board.			
Leak test and leak brazing.			
Flushing of refrigerant system using freon gas 141b.			
Flushing of refrigerant system using nitrogen gas.			
Vacuuming and recharging of freon gas.			
Test and observation.			
VAT			
SUB-TOTAL			<i>15,000.00</i>
8. Repair of Carrier 2.5 HP wall mounted inverter type air conditioning unit located at GSS.	1	UNIT	
Scope of Work:			
1. Leak test and leak brazing.			
2. Flushing of refrigerant system using freon gas 141b.			
3. Flushing of refrigerant system using nitrogen gas.			
4. Vacuuming and recharging of freon gas.			
5. Test and observation.			
VAT			
SUB-TOTAL			<i>7,000.00</i>
9. Repair of Koppel 2.0 HP window type air conditioning unit located at GSS (Records Unit)	1	UNIT	
Leak test and leak brazing.			
Flushing of refrigerant system using freon gas 141b.			
Flushing of refrigerant system using nitrogen gas.			
Vacuuming and recharging of freon gas.			
Test and observation.			
VAT			
SUB-TOTAL			<i>6,000.00</i>
Purpose: <i>For use of PCAF</i>			

Please acknowledge receipt and acceptance of this Notice within 3 working days by signing in the space provided below and email us at bacsec@pcaf.da.gov.ph upon receipt thereof.

In connection with this Notice, please submit the following documents;

1. Omnibus Sworn Affidavit that the bidder is not related to the HOPE by consanguinity or affinity up to the third civil degree;
2. Signed Purchase Order.



Republic of the Philippines
 Department of Agriculture
PHILIPPINE COUNCIL FOR AGRICULTURE AND FISHERIES
 Department of Agriculture Compound
 Elliptical Road, Diliman, Quezon City
 Tel. No. (02) 8928-8751 to 64 locals 2601-2625, email: pcafofficial@pcaf.da.gov.ph


PAGE 4 OF NOA NO. 2024-029

For inquiries, you may get in touch with Mr. Ken Ryan P. Eleazar, BAC Secretariat of PCAF at telephone numbers 8926-2147. Loc 2622

Thank you.

Very truly yours,


CYRIL L. SOLIABAN
 OIC - Deputy Executive Director

I acknowledge receipt of this Notice of Award on 4-5-24
 Name of Authorized Representative Jonathan C. Ganitano
 Signature 
 Bank Details:
 Name of Payee : Top Premiere Enterprise
 Name of Bank : Land Bank of the Philippines
 Branch : Espana Branch
 Account Number : 3721001104

